



INSPECTION REPORT

Pre-Shipment Inspection

Report No: H-21125567

INSPECTION INFORMATION

Client	Central Plumbing Industries Co., Ltd		
Supplier	HEBEI CENTRAL PLUMBING INDUSTRIES CO.,LTD		
Factory	-		
Inspection Instruction	GWI-G-GTZP-valve-036-HQT		
P.O. No.	-	P.O. Quantity	213 Pieces
Item No.	Refer to quantity sheet	Sampling Plan	Fixed sample size
Inspection Date	21/12/2021	Inspection Level	-
Inspection Sequence	Original inspection	Sample Size	40 Pieces (Actual: 38 Pieces)
Inspection Location	Tianjin, China	AQL	-
Product Description	Valve		



INSPECTION RESULT SUMMARY

Category	Conform	Not Conform	Pending
1. Quantity	X		
2. Field Test & Measurement			X
OVERALL CONCLUSION	PENDING		

Approved by HQTS Supervisor

This report reflects the facts as recorded by HQTS at the time and place of inspection. It does not relieve the manufacturers from their contractual obligations nor prejudice client's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter.

SPECIAL ATTENTION POINT (SAP)

1	Quantity	NIL
2	Field Test & Measurement	
2.1	Due to test machine failure, only 2pieces valves of DN 50 were performed tightness test.	

INSPECTION DETAILS

1. Quantity					Conform			
P.O. No.	Item No.	P.O. Qty	Shipment Qty		Packed Qty		Sample Size	
		(Piece)	(Piece)	(Carton)	(Piece)	(Carton)	(Piece)	(Carton)
-	DN 50	70	70	-	70	-	2	-
	DN 80	20	20	-	20	-	3	-
	DN 100	80	80	-	80	-	10	-
	DN125	3	3	-	3	-	3	-
	DN 150	30	30	-	30	-	10	-
	DN 200	10	10	-	10	-	10	-
Total		213	213	-	213	-	38	-

2. Field Test & Measurement				Pending		
Item		Specification	Sample Size	Conform	Not Conform	Pending
2.1	Valve tightness test	-	All samples			X
2.2	Dimension check	-	1 piece/item			X

Checking Item	Specification (mm)	Result (mm)
Valve length of DN50	-	176
Valve length of DN 80	-	199.7
Valve length of DN 100	-	226.5
Valve length of DN125	-	249
Valve length of DN 150	-	279
Valve length of DN 200	-	329

Reference Note

- | | |
|---|--|
| 1 | For DN 125, DN 100, DN 80 and DN 50, 16 was marked on valve body instead of PN10 in client's requirement |
|---|--|



DN125



DN100



DN80



DN50

- | | |
|---|--|
| 2 | For DN150 and DN200, only 'EAC' marked on valve body, but other items without 'EAC' marking. |
|---|--|



DN 200



DN 150

3. Photos

Item DN 200



Item DN 200

Item DN 200



Item DN 200

Item DN 200



Item DN 200

Item DN 200



Item DN 200



Item DN 200



Item DN 200



Item DN 200



Item DN 200



Item DN 200



Item DN 200



Item DN 200



Item DN 200



Item DN 200



Item DN 200



Item DN 200



Item DN 200



Item DN 200

DN150



DN150



DN150




DN150



DN150



DN150



DN150



DN150



DN150



DN150



DN150



DN150



DN150



DN150



DN150



DN150



DN150



DN150



DN150



DN150



DN150

DN125



DN125




DN125



DN125



DN125



DN125



DN125



DN125



DN125



DN125



DN125



DN125



DN125



DN125



DN125



DN125



DN125



DN125



DN125

DN100



DN100



DN100



DN100



DN100



DN100



DN100



DN100



DN100



DN100



DN100



DN100



DN100



DN100



DN100



DN100



DN100

DN80



DN80



DN80



DN80



DN80



DN80



DN80



DN80




DN80



DN80



DN80



DN80



DN80



DN80



DN80



DN80



DN80

DN50



DN50



DN50



DN50



DN50



DN50



DN50



DN50




DN50



DN50



DN50



DN50



DN50



DN50



DN50



DN50



DN50

Inspector:	Wang	Auditor:	3100
End of Report			